

INVESTIGATION OF CAUSES AND SUGGESTED
REMEDIES OF HOSIERY FAULTS.

BY

NIHAL RATHNAYAKE

UNIVERSITY OF MORATUWA, SRI LANKA

DISSERTATION SUBMITTED TO THE
UNIVERSITY OF MORATUWA, SRI LANKA
IN PART FULFILMENT OF THE

POST GRADUATE DIPLOMA IN TEXTILE TECHNOLOGY.

1986.

677 '86"
684.254

Project Report

DEPARTMENT OF TEXTILE TECHNOLOGY,
UNIVERSITY OF MORATUWA,
MORATUWA, SRI LANKA.

441 Thesis

78491

University of Moratuwa



78491

78491





University of Moratuwa, Sri Lanka
Electronic Theses & **MY PARENTS**
www.lib.mrt.ac.lk

TO

AND

MY SISTER.

ABSTRACT

Defects occ^uring at knitting, dyeing, linking, boarding, cutting and sewing individually or collectively give rise to faults in hosiery which are detected by the naked eye apart from the undetectable winding faults and yarn faults.

In this study these faults have been considered in eight different classes and given in tabulated form.



University of Moratuwa, Sri Lanka.
Electronic Theses & Dissertations
www.lib.mrt.ac.lk

Due to practical difficulties such as interruption to production flow and difficulties in introducing new methods, this study has been limited to a few suggestions only.

This work could be used for a more detailed study in faults in hosiery including shrinkage after dyeing of stretched nylon and acrylic for hosiery knitted fabrics.

A C K N O W L E D G E M E N T S


I wish to express my gratitude to Professor Lakdas D.Fernando, Head of the Department of Textile Technology of the University of Moratuwa, Sri Lanka, for helping and directing me to follow this course of study and the project as well.

My heartfelt thanks are due to Mr.Z.T.Bartnik, Knitting advisor, UNIDO Project, Textile Training and Services centre, Ministry of Textile Industries, Ratmalana, for his yeoman service rendered to me by guiding and encouraging me in this project.

I also extend my thanks to Mr. Michael Lohs, Managing Director, ESKIMO Fashion Knitware (Lanka) Limited for enlisting me as a trainee production executive in his company during my project work there. My thanks are due to Mr. Dharmasiri and his staff who assisted me in carrying out this work at Eskimo Fashion Knitware Ltd.

My thanks are also to Miss. Ranjane Samaranayake, Mr. R. Shanmuganathan, Mr. Kithsiri Jayalath, Mr. A. J. Kasin Ahamed and Mr. S. A. Anbahan who helped me to bring out my effort into book form.

Before I conclude my sincere thanks specially go to Dr. M. P. U. Bandara, Mr. Harris Silva and other members of the staff of the Department of Textile Technology and the Department of Computer Science and Engineering of the University of Moratuwa, Sri Lanka, for helping in this venture.



CONTENTS

ABSTRACT

1. INTRODUCTION

- 1.1 Organisation
- 1.2 Product (TIGHT)
- 1.3 Layout

2. PRODUCTION PROCEDURE

3. LITERATURE SURVEY AND GENERAL FAULTS

- 3.1 Knitted Fabric Faults (causes)
- 3.2 Knitted Fabric Faults (remedies)
- 3.3 Principles of bulking of Acrylic fibres
- 3.4 General possible faults

4. INVESTIGATION INTO CAUSES FOR PARTICULAR FAULTS.

- 4.1 Winding faults
- 4.2 Knitting faults
- 4.3 Dyeing faults
- 4.4 Linking faults
- 4.5 Boarding faults
- 4.6 Grading faults
- 4.7 Cutting faults
- 4.8 Sewing faults

5. EXPERIMENTAL PROCEDURE

- 5.1 Analysis of hosiery faults of Eskimo
- 5.2 SPECIAL PROBLEM- Length variation.

6. SUGGESTED REMEDIES FOR HOSIERY FAULTS

7. CONCLUSION.

8. APPENDIX

