

8. REFERENCES

- [1] Littelfuse.com. (2018). [online] Available at: http://www.littelfuse.com/~media/electronics/product_catalogs/littelfuse_varistor_catalog.pdf [Accessed 4 Jun. 2018].
- [2] IEEE 519-2014 - IEEE Recommended Practice and Requirements for Harmonic Control in Electric Power Systems.
- [3] K. Eda, A. Iga, and M. Matsuoka. Degradation mechanism of non-ohmic zinc oxide ceramics. *Journal of Applied Physics*, 1(5):2678-2684, January 1980.
- [4] D.Zhou, C.Zhang, and S.Gong. Degradation phenomena due to dc bias in low voltage ZnO varistors. *Materials Science and Engineering: B*, 1-3(99):412-415, May 2003.
- [5] D. Kladar, F. Martzloff and D. Natasi. TOV Effects on Surge-Protective Devices. *Power Quality Exhibition and Conference, Baltimore*, October 25-27 2005.
- [6] Y. Wen and C. Zhou. A Novel Method for Predicting the Lifetime of MOV. *IEEE transactions on power delivery*, vol. 19, no. 4, October 2004.
- [7] M.Jaroszewski, P. Kostyla, and K. Wieczorek. Effect of voltage harmonics content on arrester diagnostic result. *Proceedings of the International Conference on Solid Dielectrics (ICSD 2004), Toulouse, France*, July 2004.
- [8] Technical note on Capacitor lifetime. Rubicon Corporation. [www.rubycon.co.jp/en/products/alumi/pdf/Life.pdf].
- [9] IEEE Std C62.11-2012 IEEE Standard for Metal-Oxide Surge Arresters for AC Power Circuits (>1 kV).
- [10] M. Balci and M. Hocaoglu. On the validity of harmonic source detection methods and indices. *Proceedings of the 14th International Conference on Harmonics and Quality of Power, Bergamo, Italy*, September 2010.
- [11] R. Herrera, P. Salmeron, and S. Litran. Assessment of harmonic distortion sources in power networks with capacitor banks. *Proceedings of the 11th International Conference on Renewable Energies and Power Quality, Las Palmas de Gran Canary, Spain*, April 2011.
- [12] C.de Salles, M. L. Martinez, and A.A. de Queiroz. Ageing of metal oxide varistors due to surges. *Proceedings of the International Symposium on Lightning Protection (XI SIPDA), Fortaleza, Brazil*, October 2011.

- [13] R.A. Sargent, G. L. Dunlop, and M. Darveniza. Effects of multiple impulse currents on the microstructure and electrical properties of metal oxide varistors. *IEEE Transactions on Electrical Insulation*, 6(3):586-592, June 1992.
- [14] P.Osmokrovic, B. Loncar, S. Stankovic, and S.Vasic. Aging of the over-voltage protection elements caused by over-voltages. *Microelectronics Reliability*, 12(12): 1959 -1966, December 2002.
- [15] C.Nahm. Pulse aging behavior of ZnO-pr6o11-coo-cr2o3-dy2o3 varistor ceramics with sintering time. *Ceramics international*, 37(6):1409{1414, May 2011.
- [16] W. Sun, Y. Li, D. Zeng, R. Cai, and Z. Meng G. Yang. Investigation of voltage current characteristics of ZnO varistors under 8/20 microsecond impulse current. *The IEEE Power Engineering and Automation Conference, Wuhan, China*, September 2011.
- [17] C. Karawita and M.Raghuveer. Leakage current based assessment of degradation of MOSA using an alternative technique. *Annual Report of the Conference on Electrical Insulation and Dielectric Phenomena (CEIDP'05)*, pages 199-201, October 2005
- [18] J. He, R. Zeng, Y. Tu, S. Han, and H. Cho. Aging characteristics and mechanisms of ZnO nonlinear varistors. *Proceedings of the 6th International Conference on Properties and Applications of Dielectric Materials, Xi'an, China*, June 2000.
- [19] MATLAB Simulink Documentation. (2019). [online] Available at: <https://www.mathworks.com/help/simulink/> [Accessed 4 Jun. 2019].
- [20] Medium-voltage surge arresters production video (smaller format). (2019). [video] Available at: <https://search-ext.abb.com/library/Download.aspx?DocumentID=9AKK107046A9495&LanguageCode=en&DocumentPartId=Lower%20resolution&Action=Launch> [Accessed 19 Nov. 2019].
- [21] V.P. Rabde. Metal oxide varistors as surge suppressors. *Proceedings of the 1995 International Conference on Electromagnetic Interference and Compatibility (INCEMIC)*, Madras, India.