LIBRARY UNIVERSITY OF MORATUWA, SRI LANKA MORATUWA

LB/DON/117/2012 DAR 06/03 03

## CONSRVATION AND PRESERVATION OF COLONIAL FACADES IN HISTORIC URBAN NEIGHBORHOODS WITH SPECIAL REFERENCE TO SLAVE ISLAND

A thesis presented to the University of Moratuwa, as Master of Science degree in Architectural Conservation of Monuments and Sites.



72°10″ 72.025(04 University of Moratuwa 💓 🍋 🗤 🖉 H T ACCESSION N 104049 CLASS No.

JEEWANTHA MAGAMAGE

ACOMAS, FACULTY OF ARCHITECTURE, UNIVERCITY OF MORATUWA,


104049

11<sup>TH</sup> MAY, 2010.

## CONSRVATION AND PRESERVATION OF COLONIAL FACADES IN HISTORIC URBAN NEIGHBORHOODS WITH SPECIAL REFERENCE TO SLAVE ISLAND

3

A thesis presented to the University of Moratuwa, as Master of Science degree in Architectural Conservation of Monuments and Sites.



#### **JEEWANTHA MAGAMAGE**

ACOMAS, FACULTY OF ARCHITECTURE, UNIVERCITY OF MORATUWA,

11<sup>TH</sup> MAY, 2010.

## Declaration

I declare that this thesis represents my own work and that it has not been previously included in report submitted to this university or to another institution for a degree, postgraduate diploma or other qualification

# **UOM Verified Signature**

Signature of student



University of Moratuwa, Sri Lanka. Electronic Theses & Dissertations www.lib.mrt.ac.lk

# **UOM Verified Signature**

Professor S.M.Manawadu Course Director (ACOMAS) Department of Architecture University of Moratuwa



# **UOM Verified Signature**

Moratuwa

#### Acknowledgments

This scientific investigation, I had a discussion with Professor S.M Manawadu, professor of architecture and course director (ACOMAS) about bringing out all aspects on the urban conservation and heritage management and unfailing encouragement. Without Professor S.M. Manawadu's dedicated effort, this hierarchy would not have been successfully completed.

And I had with professor Nimal De Silva, professor of architecture and former course director (ACOMAS) about bringing out all aspects on the urban conservation and heritage management and unfailing encouragement. Without Professor Nimal De Silva's dedicated effort, this hierarchy would not have been successful completentity of Moratuwa, Sri Lanka.

Therefore, I wish to express my sindcere gratitude to Professor

S.M. Manawadu and professor Nimal De Silva.

My special grateful to Architect C.J.De seram, former course director (ACOMAS) in department of Architecture University of Moratuwa, for his guidance and encouragement.

My sincere gratitude, architecture D.P. Chandrasekhara, senior lecturer in department of architecture in university of Moratuwa for his advice from time to time.

I wish to thanks Architect Niashan Nawarathne and Mr V.P.A. De Mel, staff technical officer in department of architecture, university of Moratuwa, for many suggestions without their critical appraisal nothing would have been possible. Several persons and institutions have helped me in my work and my grateful to them for their assistance – staff of Colombo municipal council, providing voluble information's and assistance people of Slave Island for helping to find necessary information – staff of slave island police station for helping find necessary information. And grade help from Mr. Jithendra bandara for langue and grammar corrections.

Finally I wish to thank my family for the unfailing support and encouragement.



University of Moratuwa, Sri Lanka. Electronic Theses & Dissertations www.lib.mrt.ac.lk

## Contents

List of ill	ustrations	
Acknowl	edgment	
Introduc	ction	
Chapter	one	
1. Colon	ial period and its heritage in Sri Lanka	22
1.1	. Colonial history of Sri Lanka	22
	1.1.1 Sri Lanka as a colony	23
	1.1.2 As heritage of the colonial Urban neighborhoods	26
1.2	Development of the facades In colonial townships in Spiratewa Sri Lanka. and Slave Islandonic Theses & Dissertations 1.2.1 Colonial townships and their architecture	30 30
	1.2.2 The historical growth of street architecture	31
	1.2.3 Colonial streetscapes of slave island area	37
	The present characters	
	Relationship to landscape	
	Scale and proportion	
	1.2.4 Justice Akbar Mawatha in Slave Island	49

.

#### **Chapter two**

# 2. Examination of historic buildings in streetscape of Slave Island -case study

- 2.1. Selected building -soyza
  - A. Building form
  - B. roof
  - C. façade
  - D. floor
  - E. door/window
- 2.2. Selected building –postal No 125

65

### A. Building form

- B. University of Moratuwa, Sri Lanka.
  Electronic Theses & Dissertations
  www.lib.mrt.ac.lk
- D. floor
- E. door/window
- 2.3. Selected building -postal No 140

74

- A. Building form
- B. roof
- C. wall
- D. floor
- E. door/window

52

53

2.4. Selected building –postal no 140

- A. Building form
- B. roof
- C. wall
- D. floor
- E. door/window

Chapter three 3. Proposal for preservation of streetscape of Slave Island	89
3.1 identification of in courses of decay streetscape in Slave Island University of Moratuwa, Sri Lanka. Optural catories Theses & Dissertations www.lib.mrt.ac.lk Environmental	89
Manmade	
3.2 intervention agent of deterioration of streetscape	
3.2.1. Building form	98
3.2.2. roof	105
3.2.3. wall	111
3.2.4. floor	116
3.2.5. door/window	118
3.2.6. others	124

81

Chapter four 4. Curative Proposal for preservation of	
historic streetscape	127
4.1. Recommendations	128
4.2. Design guide lines- conservation of the slave island (Akbar Street) as a colonial streetscape.	129
The basic frame	129
The parapet or cornice	132
The sign band	134
Awnings University of Moratuwa, Sri Lanka. Electronic Theses & Dissertations The secret cont base www.lib.mrt.ac.lk	134 137
Display window	138
Entryways	140
Signage	141
Lighting	143
Colors	143
Pavement and other street related items	144

Conclusion	147
Bibliography	150

### List of illustrations

Figure 1.1 Country's history left impression through building of architectural styles

Figure 1.2 It is important to understand because buildings are often eclectic and combined the best elements of different styles

Figure 1.3 Facing of the street, become a special

Figure 1.4 No evidence to development of streetscape on Slave Island within Portuguese and Dutch period

Figure 1.4a Development of the colonial stire etstapeting Slave Island

Figure 1.5 Electronic Theses & Dissertations Www.lib.mrt.ac.lk Grid-iron Street Patten with buildings, representing colonial street architecture. Facing of the street become special

Figure 1.6 Historically, most identified neighborhoods

Figure 1.6a historically, most identified neighborhoods

Figure 1.7 Relation to the landscape

Figure 1.8 Justice Akbar mawatha

Figure 2.1 The Main elements of a streetscape,

Figure 2.2 Slave Island first emerged as a suburb Figure 2.3 Historical building form still remaining with poor strength.

Figure 2.4 Has been modified

Figure 2.5 cracked walls

Figure 2.6 In the short term, the result of this action on piece of stone is loss of from

Figure 2.7 Historical roof with mordent roofing sheet,

Figure 2.7a yet historical roof form is still present with poor maintenance.

Figure 2.8 If trees cover a the state of Moratuwa, Sri Lanka. the state of Moratuwa, Sri Lanka. the state of Moratuwa, Sri Lanka. www.lib.mrt.ac.lk

Figure 2.8a. The presence of efflorescence on a walls

Figure 2.8b while most of the down pipes have been corroded

Figure 2.8c to remedy these decayed walls some occupants have resorted to using modern decorative solutions

Figure 2.8d Due to the poor maintenance system and incorrect repairing methods

Figure 2.9 No evidence about the historical floor

Figure 2.10 Upper floor windows are present in the historical form yet they have been weathered Figure 2.10a there are no evidences historical entrance ways,

Figure 2.11 The building with steel structures, by the outlook of form seems strong

Figure 2.11a If movement occurs because of this failure

Figure 2.12Right side of the roof are highly dilapidated and exposed to rain water

Figure 2.13 The façade of the building is identifiable form

Figure 2.13a The upper floor big balcony with the dilapidated

Figure 2.15 Symmetrical square of Moratuwa, Sri Lanka. Symmetrical square of the Thousa & Thousa used as entrance for shops

Figure 2.16 The historical building form outlook of from seems strong

Figure 2.16a Large singes and newly modified steel doors are obstructing building form also front elevation.

Figure 2.16b Due to the heavy traffic conjunction, historical buildings were not designed to absorbing changers in its surrounding.

Figure 2.17 The historical roof was available but willing to proper maintenance system

Figure 2.17a The presence of efflorescence on a wall shows the places where water Figure 2.18 The façade is covered by signboards of present occupants.

Figure 2.19 No evidence about the historical floor,

Figure 2.20 Symmetrical arches of the ground floor are being used as entrance for shops

Figure 2.21 Those deformities are mostly temporary except in the case of "Building 137" which has been changed from its colonial form permanently

Figure 2.22 The roof of the building is finished with asbestos roofing sheet

Figure 2.22a The parapet wallon a building has completely been removed by the residents due to safety goncerns. lk

Figure 2.23 The ground floor symmetrical archers are placed as main entrance and upper

Figure 2.24 No evidence about the historical floor

Figure 2.25 There are different types of doors in the ground floor of these buildings.

Figure 3.1 When comparing the three buildings, their colonial form is uniform, though they have been subject to some deformities owing to various usages and human activities

Figure 3.1a "Building no 137" which has been changed from its colonial form permanently. Figure 3.1b Removing the aforesaid deformity -building No 137

Figure 3.2 Changing only the outer appearance of the building to a colonial form while maintaining those deformities- building No 137

Figure 3.3 Using canopies is the next main deformation.

Figure 3.3a Introducing an identical canopy to all

Figure 3.4 The reason behind this is the narrower eave

Figure 3.5 When compared with the modified roof of the Soyza building

Figure 3.5a University of Moratuwa, Sri Lanka. Except for Soy and the Buildinghises 25, roofs dioother two buildings have been modified from the historical form

Figure 3.6 Since the eave of the Soyza building is much narrower the upper storey walls are heavily decayed.

Figure 3.7 That is recreating the historical roof form of these buildings by building back the parapet walls of these buildings

Figure 3.8 This can be remedied by adding the same canopies adopted by the occupants of the soyza building

Figure 3.9 Firstly, the hoardings that exist covering these historical facades should be removed

Figure 3.10 The modifications and restorations done Figure 3.11 Façade decorations of all these buildings are mostly repetitive and symmetrical therefore the lost decorations can be easily identified

Figure 3.11a Façade decorations

Figure 3.11b Façade decorations

Figure 3.11c The occupants have changed the decorations/Façade plaster according to their whim

Figure 3.12 These irregular door styles should be changed

Figure 3.12a All upper storever dows are in dire condition today. Figure 3.13

A close study can reveal some important evidences of their door and window styles.

Figure 3.14 These buildings presently due to changes that have been effected to match the commercial purposes of these buildings thereby changing the historical view of the building

Figure 3.14a The ground floor shop front should be planned so as to enhance the present usage.

Figure 3.15 The decayed window decorations can be seen

Figure 4.1 The basic frame

Figure 4.2 The parapet or cornice Figure 4.3 The sign band

Figure 4.4 Awnings

Figure 4.5 The storefront base

Figure 4.6 Display window

Figure 4.7 Entryways

Figure 4.8 Signage

Figure 4.9 Colors

Figure 4.10



University of Moratuwa, Sri Lanka. Electronic Theses & Dissertations www.lib.mrt.ac.lk

Pavement and other street related items